

Drive Safe, Arrive Safe.



- Always follow equipment safety procedures.
- Stay alert while operating mobile equipment.



More than 60 miners lost their lives in accidents involving mobile equipment at the nation's surface mines between 2005 and 2009.

Those 60 fatalities were **nearly half of all fatalities** at surface mines and nearly one-quarter of all mining fatalities for those years.

Distracted driving kills.

Key Points:

1. Conduct pre-operation safety inspections.
2. Pay attention and follow established safe driving practices.
3. Know your surroundings and follow all posted safety warnings.
4. Report identified hazards that may result in a driving safety and mobile equipment operating accident.

